

NAPOMENA:
Obzirom da projektant nije raspolažao dovoljno preciznim podacima o kolskim prilazima objektima, obaveza izvođača radova je da na osnovu konsultacija sa nadzornim organom na kolskim prilazima izvrši prekid ivične linije i/ili neisprekidane ravnice linije i da obeleži isprekidanu liniju rastera 1+1.
NOTE:
Since the designer did not have sufficient precise data on the accessibility of gateway entrance to objects, it is the obligation of the contractor to interrupt the edge lines and / or continuous cental lines and mark the line 1 + 1 , on the basis of consultations with the supervisory authority

